

BROOKFIELD PUBLIC SCHOOLS

PUBLIC FORUM #1

EXISTING CONDITIONS ANALYSIS



BROOKFIELD PUBLIC SCHOOLS / AGENDA

- 1. INTRODUCTIONS
- 2. OUTLINE GOALS OF THE PROJECT
- 3. EXISTING CONDITIONS INITIAL FINDINGS
- 4. WORKSHOP & COMMUNITY INPUT
- 5. NEXT STEPS, Q & A



INTRODUCTIONS / A COLLABORATIVE APPROACH

STRATEGIC FACILITIES PLANNING COMMITTEE

Ms. Eve Sturdevant

Committee Chairperson
Board of Education Member

Dr. John W. Barile

Superintendent of Schools

Mr. Paul Checco

Municipal Building Committee Chairperson

Mrs. Eileen Koch

Board of Finance Member

Mr. Josh Flowers

Municipal Building Committee Member

Mrs. Joy Greenstein

Board of Education Member

Mrs. Sue Slater

Board of Selectmen

Mrs. Debbie Brooks

Board of Education Member

Mrs. Christing Zimmerman

PTO President

Mr. Paul Loftus

Community Member

CONSULTANT TEAM

TECTON ARCHITECTS

Architecture & Programming Jeff Wyszynski, AIA Stephen Melingonis, AIA MILONE & MACBROOM

Site, Civil, Landscape, Planning Ryan Chmielewski , LA CES

MEP Engineering Derek Bride SZEWCZAK ASSOCIATES

Structural Engineering Peter Celella, PE

GOALS OF THE PROJECT/ MASTER PLAN FOR THE FUTURE

- Analysis of Existing Conditions & Educational Needs
- Engage community & explore responsive solutions
- Sustainable approach to address facility and educational needs
- Combination of Capital, Maintenance and Life Safety projects
- Long Range Master Plan for All Schools

COMMUNICATION/ KEEPING THE LINES OPEN

- Strategic Facilities Committee Meeting Dates
 - (4/4 @ 6:30 p.m., 5/1 @ 6 p.m., 5/22 @ 6 p.m.)
 - Pocono Road, 2nd floor conference room
- Upcoming Forums
 - June 7th Conceptual Design Review Options for the Community
 - Date TBD- 10 Year Master Plan & First Phase
- Updates go to our Website:
 https://sites.google.com/a/brookfieldps.org/bpssfc/
- Join Us on Facebook: https://www.facebook.com/bpssfc

EXISTING CONDITIONS INITIAL FINDINGS

CURRENT STATUS/ WORK COMPLETED SO FAR

- Collection of existing conditions
- Analysis of physical deficiencies
- Proposed Recommendations to remediate deficiencies
- Programmatic Discussions
 - Stakeholder interviews
 - Develop current and future needs
- Initial State Reimbursement Analysis Options & Impacts

BROOKFIELD SCHOOLS / FACILITIES OVERVIEW

AVERAGE BUILDING AGE: 60 YEARS | AVERAGE ADDITION AGE: 17 YEARS

BUILDING	YEAR BUILT	CURRENT AGE	K-12 ENROLLMENT
CENTER ELEMENTARY	1937, 1997 Addition	80, 20	359
HUCKLEBERRY HILL ELEMENTARY	1960, 1993 Addition	57, 24	537
WHISCONIER MIDDLE	1970, 2001 Addition	47, 16	918
BROOKFIELD HIGH	1959, 2006 Renovation	58, 11	865



No building has ever been fully renovated or modernized since being built.

FORMAT/ EXISTING CONDITIONS

On site walkthrough, general observations and analysis of conditions

- 1. Site overall layout, accessibility, code, useful life condition, safety/security, parking, sidewalks, lighting, drainage, utilities, and fields
- 2. Structure type, code, useful life, condition, identification of specific concerns
- 3. Architecture code, accessibility, life safety, useful life, condition, safety/security
 - 1. Exterior roofs, walls, soffits, windows, doors, and features of the building
 - 2. Interior finishes (doors, walls, ceilings, millwork, fixtures, lighting)
- 4. Building Systems Survey code, life safety, useful life of equipment, comfort & control
 - 1. Plumbing
 - 2. Mechanical
 - 3. Electrical
 - 4. Fire Protection & Alarms

FORMAT/ EXISTING CONDITIONS


Identification & Prioritization (Scale 1 to 5)

A ranking for each item was given from 1-5 to indicate the priority of attention required. A ranking of 1 indicates a material requiring prompt attention, while a ranking of 5 indicates the material is in good condition and does not require maintenance or replacement. Accessibility compliance is identified as (A)









SITE/CIVIL

- 1. Roadways/Parking
- 2. Walks
- 3. Paved Play
- 4. Grass Play
- 5. Playgrounds
- 6. Storm Drainage
- 7. Lighting

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
CENTER ELEMENTARY	1937, 1997 Addition	80, 20	359






STRUCTURE

- 1. WOOD / STEEL
- 2. SPALLING CONCRETE
- 3. WATER INFILTRATION
- 4. MINOR SLAB CRACKS



BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
CENTER ELEMENTARY	1937, 1997 Addition	80, 20	359









ARCHITECTURE

- 1. EXTERIOR
- 2. INTERIOR

BUILDING SYSTEMS

- FIRE PROTECTION, ALARMS, SECURITY
- 2. PLUMBING
- 3. MECHANICAL
- 4. ELECTRICAL

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
CENTER ELEMENTARY	1937, 1997 Addition	80, 20	359



SUMMARY

- a) PAVEMENT CONDITION AND ACCESSIBILITY
- b) PLAYGROUNDS AND EMERGENCY ACCESS @ PERIMETER
- c) STRUCTURE DIFFICULT TO EXPAND BY CODE DUE TO TYPE (WOOD FRAME)
- d) PORTIONS OF EXTERIOR ENVELOP ARE IN POOR CONDITION WINDOWS/WALLS
- e) NOT ENERGY EFFICIENT (100% EXHAUST)
- f) ALL BUILDING SYSTEMS PAST THE END OF THEIR EXPECTED USEFUL LIFE



SITE/CIVIL

- 1. ROADWAYS/PARKING
- 2. WALKS
- 3. PAVED PLAY
- 4. GRASS FIELDS
- 5. SKINNED INFIELDS
- 6. PLAYGROUNDS
- 7. OTHER:
 GARDEN/OUTDOOR
 CLASSROOM
- 8. STORM DRAINAGE
- 9. LIGHTING

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
HUCKLEBERRY HILL ELEMENTARY	1960, 1993 Addition	57, 24	537







STRUCTURE

- STEEL, OPEN WEB JOISTS &
 MTL. DECK CONCRETE SLAB
- 2. TECTUM ROOF PANELS
- 3. FAIR CONDITION OVERALL
 NO SIGNIFICANT
 OBSERVATIONS

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
HUCKLEBERRY HILL ELEMENTARY	1960, 1993 Addition	57, 24	537







ARCHITECTURE

- . EXTERIOR
- 2. INTERIOR

BUILDING SYSTEMS

- FIRE PROTECTION, ALARMS, SECURITY
- 2. PLUMBING
- 3. MECHANICAL
- 4. ELECTRICAL

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
HUCKLEBERRY HILL ELEMENTARY	1960, 1993 Addition	57, 24	537



SUMMARY

- a) PAVEMENT CONDITION AND ACCESSIBILITY
- b) PLAYGROUNDS AND IMPROVE SITE DRAINAGE
- c) BUILDING NOT FULLY ACCESSIBLE
- d) SOME FINISHES REACHED END OF USEFUL LIFE (TOILETS)
- e) NOT ENERGY EFFICIENT (ALL ELECTRIC HEAT)
- f) CODE COMPLIANT AT TIME OF CONSTRUCTION, BUT NO SPRINKLER SYSTEMS



SITE/CIVIL

- 1. ROADWAYS/PARKING
- 2. WALKS
- 3. PAVED PLAY
- 4. GRASS FIELDS
- 5. SKINNED INFIELDS
- 6. PLAYGROUND
- 7. STORM DRAINAGE
- 8. LIGHTING

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
WHISCONIER MIDDLE	1970, 2001 Addition	47 , 16	918









STRUCTURE

- . STEEL BEAMS, METAL
 DECK, CONCRETE SLAB
- 2. DETERIORATION OF SOUTH
 FAÇADE AT GYM MOISTURE
- REPOINTING, FLASHING
 WEEPS TO EXTEND
 LONGEVITY

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
WHISCONIER MIDDLE	1970, 2001 Addition	47 , 16	918







ARCHITECTURE

- 1. EXTERIOR
- 2. INTERIOR

BUILDING SYSTEMS


- FIRE PROTECTION, ALARMS, SECURITY
- 2. PLUMBING
- 3. MECHANICAL
- 4. ELECTRICAL

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
WHISCONIER MIDDLE	1970, 2001 Addition	47 , 16	918



SUMMARY

- a) PAVEMENT CONDITION AND ACCESSIBILITY
- b) LACKS EMERGENCY ACCESS AT PERIMETER
- c) FAIR CONDITION, ISOLATED ENVELOP CONCERNS AT GYM LONGEVITY OF MATERIALS
- d) MULTIPLE ADDITIONS, FRAGMENTED BUILDING MANY BUILDING JOINTS, DISSIMILAR AESTHETIC
- e) BUILDING SYSTEMS OF VARIOUS AGES, ALL AT OR NEAR END OF USEFUL LIFE
- f) FLOURESCENT LIGHTING, NEEDS SIGNIFICANT REPAIR



SITE/CIVIL

- 1. ROADWAYS/PARKING
- 2. WALKS
- 3. BASKETBALL COURT
- 4. TENNIS COURTS
- 5. GRASS FIELDS
- 6. SKINNED INFIELDS
- 7. SYNTHETIC TURF
- 8. RUNNING TRACK
- COURTYARDS
- 10. STORM DRAINAGE
- 11. LIGHTING

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
BROOKFIELD HIGH	1959, 2006 Renovati on	58, 11	865





STRUCTURE

- STEEL, OPEN WEB JOISTS, CAST IN PLACE
- 2. SOME AREAS OF
 DETERIORATION OF CAST
 IN PLACE SPALLING



BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
BROOKFIELD HIGH	1959, 2006 Renovati on	58, 11	865







ARCHITECTURE

- I. EXTERIOR
- 2. INTERIOR

BUILDING SYSTEMS

- FIRE PROTECTION, ALARMS, SECURITY
- 2. PLUMBING
- 3. MECHANICAL
- 4. ELECTRICAL

BUILDING	YEAR	CURRENT	K-12
	BUILT	AGE	ENROLLMENT
BROOKFIELD HIGH	1959, 2006 Renovati on	58, 11	865



SUMMARY

- a) PAVEMENT CONDITION AND ACCESSIBILITY
- b) TENNIS COURT EROSION & SETTLING BEHIND SCHOOL
- c) FAIR CONDITION OF BUILDING ENVELOP, MINOR CONCERNS OBSERVED
- d) SOME FINISHES REACHED END OF LIFE (BOYS SHOWERS) & SPRALLING INEFFICIENT LAYOUT
- BUILDING SYSTEMS OF VARIOUS AGES, ALL AT OR NEAR END OF USEFUL LIFE
- f) BUILDING PARTIALLY HEATED WITH STEAM, LACKS TEMP CONTROL

EXISTING CONDITIONS / CONCLUSIONS















WORKSHOP & PUBLIC INPUT

ASK, LISTEN, UNDERSTAND

PUBLIC WORKSHOP/ ASK, LISTEN, UNDERSTAND

- Open platform to ask questions, express concerns, and voice opinions
- Beginning stages of this effort the time is now
- Interactive & continuous process
- Responsive to entire community

Tonight - Discussion to identify concerns and need, group, then prioritize.

PUBLIC WORKSHOP/ ASK, LISTEN, UNDERSTAND

- Why did you attend tonight?
- What is important to you?
- What do you see as a priority?
- What works well? What doesn't?
- What do you believe is the greatest need?
- Do you believe there is a need?
- If you could change one thing, what would it be?
- What would you change about previous projects?





Strategic Facilities Committee Survey

http://tiny.cc/bps-sfc





NEXT STEPS

NEXT STEPS/ WHAT TO EXPECT

- 1. Summarize findings of condition study
- 2. Prioritize needs Immediate, mid-range, long term
- Develop options and conceptual designs (April May)
- 4. Review options with community & state (Summer)
- 5. Finalize master plan & prioritize first project (Summer/Fall)
- 6. Public Awareness Sessions (Summer/Fall)
- 7. Fall Referendum (November 6th)



THANK YOU

