

# Radon Testing Results - Harney ESD Service Center

## Action Level is 4.0 pCi/L

Site Name	Building Name	Room Description (per floor plan)	Kit serial #	Date Sampled	Type of test	Results (pCi/L)
Harney ESD Service Center	ESD Building	Computer Room A	9545423	12/07/20	Detector Kit	4.0
Harney ESD Service Center	ESD Building	Computer Room D	9545619	12/07/20	Duplicate	3.9
Harney ESD Service Center	ESD Building	Conference Room 2	9545412	12/07/20	Detector Kit	1.1
Harney ESD Service Center	ESD Building	Conference Room 3	9545637	12/07/20	Detector Kit	0.8
Harney ESD Service Center	ESD Building	Kitchen A	9545625	12/07/20	Detector Kit	0.9
Harney ESD Service Center	ESD Building	Kitchen D	9545632	12/07/20	Duplicate	1.4
Harney ESD Service Center	ESD Building	Large Conference Room A	9545647	12/07/20	Detector Kit	1.1
Harney ESD Service Center	ESD Building	Large Conference Room D	9545646	12/07/20	Duplicate	1.0
Harney ESD Service Center	ESD Building	Library	9545413	12/07/20	Detector Kit	1.3
Harney ESD Service Center	ESD Building	Lobby	9545422	12/07/20	Detector Kit	1.2
Harney ESD Service Center	ESD Building	Lobby Office	9545421	12/07/20	Detector Kit	1.4
Harney ESD Service Center	ESD Building	Office 1	9545430	12/07/20	Detector Kit	1.2
Harney ESD Service Center	ESD Building	Office 1b	9545414	12/07/20	Blank	< 0.3
Harney ESD Service Center	ESD Building	Office 2	9545602	12/07/20	Detector Kit	1.2
Harney ESD Service Center	ESD Building	Office 25-1 A	9545408	12/07/20	Detector Kit	1.3
Harney ESD Service Center	ESD Building	Office 25-1 B	9545406	12/07/20	Blank	< 0.3
Harney ESD Service Center	ESD Building	Office 25-2	9545620	12/07/20	Detector Kit	1.8
Harney ESD Service Center	ESD Building	Office 25-3	9545411	12/07/20	Detector Kit	1.4
Harney ESD Service Center	ESD Building	Office 3	9545639	12/07/20	Detector Kit	0.7
Harney ESD Service Center	ESD Building	Office 4	9545605	12/07/20	Detector Kit	1.3
Harney ESD Service Center	ESD Building	Office A	9545429	12/07/20	Detector Kit	3.7
Harney ESD Service Center	ESD Building	Office B	9545407	12/07/20	Detector Kit	3.9
Harney ESD Service Center	ESD Building	Office C	9545627	12/07/20	Detector Kit	3.5
Harney ESD Service Center			9537802		Spike	29.8

ACTION REQUIRED

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- [1 number] of spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.