

Risk Management Department

201 West Burleigh Boulevard - Tavares, FL 32778-2496 (352) 253-6600 - Fax: (352) 253-6674 - www.lake.k12.fl.us

Occupant Name: Mascotte Charter Elementary Inspection Date: 10/6/2020

Address:460 Midway AvenueInspectionType:ACFI InspectionCity:MascotteInspected By:Joey Graham

Insp. Result	Location	Code Set	Code
Deficiency	01-115 Custodial Laundry	FL NFPA 01 2015 Chapter 11 Building Services	11.5.4 - Maintenance - Repair exhaust for kiln.
	Inspector Comments: Repair dryer exhaust vent line behind dryer.		
Deficiency	01-126B Restroom	FL NFPA 101 2015 Chapter 7 Means of Egress	7.2.1.5.1 - Maintenance - Door drags on frame - must be adjusted to open freely.
	Inspector Comments:	Door drags on frame.	
Deficiency	01-133 Custodial Storage	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repair emergency light - path of egress at floor level.
	Inspector Comments: The wall pack emergency light does not work.		
Deficiency	01-146 Mechanical Room	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repair emergency light - path of egress at floor level.
	Inspector Comments:	The wall pack emergency light	does not work.
Deficiency	01-158A Kiln Room	FL NFPA 01 2015 Chapter 13 Fire Protection Systems	13.6.4.1.1 - Maintenance - Fire extinguisher date is expired.
	Inspector Comments:	Fire extinguisher is out of date	
Deficiency	01-212 Electrical Room	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repair emergency light - path of egress at floor level.
	Inspector Comments:	The wall pack emergency light	does not work.
Deficiency	02-104 PE Storage	FL NFPA 101 2015 Chapter 7 Means of Egress	7.9.2.1.1 - Maintenance - Repair emergency light - path of egress at floor level.
	Inspector Comments:	The wall pack emergency light	does not work.

Inspector Comments: I found a plug in type air freshener in building 01- 103A Extended Day Care room. Please remind staff that theses type devices are not allowed.

Inspector will return on or after 11/9/2020

Thank you for your cooperation in keeping our facility safe.

Company Representative:

Principal Mayhugh : Rego

Principal Mayhugh - Rego

10/6/2020

Inspector:

Joey Graham 10/6/2020

Ref: 188