



EMSL Analytical, Inc.

200 Route 130 North, Cinnaminson, NJ 08077

Phone: (856) 303-2500 Fax: (856) 858-4571 Email: EnvChemistry2@emsl.com

Attn:

Michael Menz
Menz Industrial Hygiene Services
286 Sunset Rd
Barrington, NJ 08007

Phone: (856) 628-6020

Fax:

7/15/2020

The following analytical report covers the analysis performed on samples submitted to EMSL Analytical, Inc. on 7/13/2020. The results are tabulated on the attached data pages for the following client designated project:

Pemberton HS

The reference number for these samples is EMSL Order #012007177. Please use this reference when calling about these samples. If you have any questions, please do not hesitate to contact me at (856) 303-2500.

Approved By:

Phillip Worby, Environmental Chemistry
Laboratory Director



The test results contained within this report meet the requirements of NELAP and/or the specific certification program that is applicable, unless otherwise noted.
NELAP Certifications: NJ 03036, NY 10872, PA 68-00367, CA ELAP 1877

The samples associated with this report were received in good condition unless otherwise noted. This report relates only to those items tested as received by the laboratory. The QC data associated with the sample results meet the recovery and precision requirements established by the NELAP, unless specifically indicated. All results for soil samples are reported on a dry weight basis, unless otherwise noted. This report may not be reproduced except in full and without written approval by EMSL Analytical, Inc.

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012007177

CustomerID: INDA25

CustomerPO:

ProjectID:

Attn: **Michael Menz**
Menz Industrial Hygiene Services
286 Sunset Rd
Barrington, NJ 08007

Phone: (856) 628-6020
 Fax:
 Received: 07/13/20 2:35 AM

Project: **Pemberton HS****Analytical Results**

Client Sample Description 0713-1
SE corner of gym
Collected: 7/13/2020 9:04:00 AM
Lab ID: 012007177-0001

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:09 SW
------	---------	----	------------	--------------	-------------------

Client Sample Description 0713-2
SW are of gym
Collected: 7/13/2020 9:06:00 AM
Lab ID: 012007177-0002

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:11 SW
------	---------	----	------------	--------------	-------------------

Client Sample Description 0713-3
NE area of gym
Collected: 7/13/2020 9:08:00 AM
Lab ID: 012007177-0003

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:13 SW
------	---------	----	------------	--------------	-------------------

Client Sample Description 0713-4
NW area of gym
Collected: 7/13/2020 9:10:00 AM
Lab ID: 012007177-0004

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:15 SW
------	---------	----	------------	--------------	-------------------

Client Sample Description 0713-5
NE area of wrestling room
Collected: 7/13/2020 9:19:00 AM
Lab ID: 012007177-0005

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:17 SW
------	---------	----	------------	--------------	-------------------

**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077

Phone/Fax: (856) 303-2500 / (856) 858-4571

<http://www.EMSL.com>EnvChemistry2@emsl.com

EMSL Order: 012007177

CustomerID: INDA25

CustomerPO:

ProjectID:

Attn: **Michael Menz**
Menz Industrial Hygiene Services
286 Sunset Rd
Barrington, NJ 08007

Phone: (856) 628-6020
 Fax:
 Received: 07/13/20 2:35 AM

Project: **Pemberton HS****Analytical Results**

Client Sample Description 0713-6
SE area of wrestling room
Collected: 7/13/2020 9:21:00 AM
Lab ID: 012007177-0006

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:25 SW
------	---------	----	------------	--------------	-------------------

Client Sample Description 0713-7
NW area of wrestling room
Collected: 7/13/2020 9:24:00 AM
Lab ID: 012007177-0007

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:27 SW
------	---------	----	------------	--------------	-------------------

Client Sample Description 0713-8
SW area of wrestling room
Collected: 7/13/2020 9:26:00 AM
Lab ID: 012007177-0008

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.19 µg/m³	7/14/2020 SW	07/15/20 10:29 SW
------	---------	----	------------	--------------	-------------------

Client Sample Description 0713-9
QA Blank
Collected: 7/13/2020
Lab ID: 012007177-0009

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.010 µg/tube	7/14/2020 SW	07/15/20 10:31 SW
------	---------	----	---------------	--------------	-------------------

Client Sample Description 0713-10
QA Blank
Collected: 7/13/2020
Lab ID: 012007177-0010

Method	Parameter	Result	RL Units	Prep Date & Analyst	Analysis Date & Analyst
--------	-----------	--------	----------	---------------------	-------------------------

METALS

6009	Mercury	ND	0.010 µg/tube	7/14/2020 SW	07/15/20 10:33 SW
------	---------	----	---------------	--------------	-------------------

Definitions:

MDL - method detection limit

J - Result was below the reporting limit, but at or above the MDL

ND - indicates that the analyte was not detected at the reporting limit

RL - Reporting Limit (Analytical)

D - Dilution Sample required a dilution which was used to calculate final results

EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAININGIndustrial Hygiene
Chain of Custody
EMSL Order Number (Lab Use Only):

012007177

EMSL ANALYTICAL, INC.
200 ROUTE 130 NORTH
CHINA MINSON, NJ 08077
PHONE: (800) 220-3675
FAX: (856) 858-3502

Report To Contact Name: MICHAEL P MENZ, CIH		Bill To Company:		Client ID #: 1NDAS25
Company Name: MENZ IND. HYGIENE SERVICES		Attention To:		
Street: 256 SUNSET RD.		Street:		
City: BARRINGTON	State/Province: NJ	Zip/Postal Code: 08007	City:	State/Province:
Phone: 856-628-6000 Fax:		Phone:		Fax:
Project Name: Pemberton HS		Email Results To: mpmenz@cih.com		U.S. State where Samples Collected: NJ
# Samples in Shipment: 10	Date of Shipment: 7/13/20	Purchase Order:	Sampled By (Signature): Muel CPMG	

Turnaround Time (TAT) - Please Check: If No Selection Made, Standard 2 Week TAT Will Apply						Media Type: SKC Canister		Manufacturer/Part #: 326-17-1A Lot #: 13010	
☐ 2 Week	☐ 1 Week	☐ 4 Day	☐ 3 Day	☒ 2 Day	☐ 1 Day	☐ Other (Call Lab)			

Client Sample ID	Sample Date	Location	Description	Sample Type	Flow (lpm)	Sample Time On	Sample Time Off	Air Volume	Analyte Name	Media	Comments
0713-1	7/13/20	SE corner of gym		Area Personal	0.2	9:04	1:09 pm	53	Mercury		
0713-2	7/13/20	SW area of gym		Area Personal	0.2	9:06	1:31 pm	53	N108H		
0713-3	7/13/20	NE area of gym		Area Personal	0.2	9:08	1:33 pm	53	6009		
0713-4	7/13/20	NW area of gym		Area Personal	0.2	9:10	1:35 pm	53			
0713-5	7/13/20	NE area of wrestling room		Area Personal	0.2	9:19	1:44 pm	53			
0713-6	7/13/20	SE area of wrestling room		Area Personal	0.2	9:21	1:46 pm	53			
0713-7	7/13/20	NW area of wrestling room		Area Personal	0.2	9:24	1:49 pm	53			
0713-8	7/13/20	SW area of wrestling room		Area Personal	0.2	9:26	1:51 pm	53			

Note: Most NIOSH and OSHA methods require field blanks. It is the IH field sampler's responsibility to submit the proper number of field blanks and duplicates.

Released By: Muel CPMG	Date: 7/13/20 2:35pm	Received By: [Signature]	Date: 7/13/20 2:35pm
Comments: cotanmeter NJ02556			

Contact client change TAT 2 days 7/13 CP
Client confirmed 2 day TAT 7/13 CP10 of 1 pages
0713-9 } 2A blanks - 0 volume
0713-10 }
108H
6009
108H
6009