School	Project	Fact	Construction Package	Status
School	Phase	Sheet	construction ruckage	Status
	1111000	No.		
Bailey APAC Middle	1	SL	Upgrade Science Labs	Construction
Bailey APAC Middle	1	1	Structural Repair	Construction
Bailey APAC Middle	1	2	Site Drainage & Soil Erosion Control	Construction
Bailey APAC Middle	1	3	Exterior & Interior Door Repairs & Replacement	Remaining
Bailey APAC Middle	1	4	Restroom Renovations	Remaining
Bailey APAC Middle	1	5	Upgrade Exterior and Interior Lighting	Remaining
Bailey APAC Middle	1	6	Electrical Upgrades	Remaining
Bailey APAC Middle	1	7	Handicapped Access	Construction
Bailey APAC Middle	1	8	Interior Wall Repair	Remaining
Bailey APAC Middle	1	9	Auditorium and Gym Floor Upgrade	Remaining
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Baker Elementary	2	1	Electrical Upgrades	Construction
Baker Elementary	2	2	Interior Painting	Construction
Baker Elementary	2	3	Building Entry Facade Upgrade	Construction
Baker Elementary	2	4	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Bates Elementary	2	1	Exterior and/or Interior Painting	Completed
Bates Elementary	2	2	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
Blackburn Middle	1	No.	Clean Exterior Building Facedo	Completed
Blackburn Middle	1	2	Clean Exterior Building Façade Upgrade Exterior and Interior Lighting	Completed TBD
Blackburn Middle		3		
Blackburn Middle	1		Repair Entry Walkway	Completed Construction
School	2 Droinet	SL	Upgrade Science Labs	
School	Project Phase	Fact Sheet	Construction Package	Status
	Pilase	No.		
Boyd Elementary	1	1	Exterior & Interior Door Replacement	Completed
Boyd Elementary	1	2	Replace Exterior Damage	Completed
Boyd Elementary	1	2	Exterior Concrete Repair	33
Boyd Elementary	1	3	Restroom Renovation	Construction
Boyd Elementary	1	4	Upgrade Exterior and Interior Lighting	Completed
Boyd Elementary	1	5	Electrical Upgrades	Completed
Boyd Elementary	1	6	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
5611001	Phase	Sheet	Construction Fundage	Status
		No.		
Brinkley Middle	2	SL	Upgrade Science Labs	Construction
Brinkley Middle	2	1	Window Replacements	Construction
Brinkley Middle	2	2	Upgrade Heating, Ventilation,	Completed
· .			and Air Conditioning Systems	
Brinkley Middle	2	3	Install Canopy from Staff Parking Lot to Building	Completed
Brinkley Middle	2	Added	Restroom Renovations	Construction

School	Project	Fact	Construction Package	Status
	Phase	Sheet	Ĭ	
		No.		
Callaway High	1	SL	Upgrade Science Labs	Completed
Callaway High	1	1	Site Drainage and Soil Erosion	Remaining
			Control	
Callaway High	1	2	Lab Chemical Storage Upgrade	Completed
Callaway High	1	3	Exterior and Interior Door	Completed
			Replacements	
Callaway High	1	4	Bleacher Repair (Gym)	Completed
Callaway High	1	5	HVAC	Completed
Callaway High	1	6	Reroofing	Completed
Callaway High	1	7	Restroom Renovations	Completed
Callaway High	1	8	Exterior Lighting	Completed
Callaway High	1	9	Repair Parking Lot	Remaining
Callaway High	1	10	Electrical Upgrades	Completed
Callaway High	1	11	Building Entry Façade Upgrade	Completed
Callaway High	1	12	Add Parking at East Building Corner	Completed
Callaway High	1	13	Repair and Widen Pedestrian Walkways	Completed
Callaway High	1	14	Upgrade Building Walkway	Completed
Callaway High	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Capital City Alternative	1	1	Site Drainage and Soil Erosion Control	Completed
Capital City Alternative	1	2	Upgrade HVAC System	TBD
Capital City Alternative	1	3	Restroom Renovation	Completed
Capital City Alternative	1	4	Upgrade Exterior and Interior Lighting	Completed
Capital City Alternative	1	5	Resurface Parking Lots	Completed
Capital City Alternative	1	6	Electrical Upgrades	TBD
Capital City Alternative	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Cardozo Middle	2	1	Walkway Repair	Design
Cardozo Middle	2	2	Interior Painting	Completed
Cardozo Middle	2	3	Upgrade Exterior Lighting	Completed
Cardozo Middle	2	4	Repair Drainage in Front of Parking Lot	Design
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Career Development Center	1	1	Repair Building Entry Brick Pavers	Completed
Career Development Center	1	2	Exterior Door Replacements	Completed
Career Development Center	1	3	Removal of Carpet in various Rooms and Install Tile Flooring	Completed
Career Development Center	1	4	Upgrade HVAC System	Completed
Career Development Center	1	5	Restroom Renovation	Completed
Career Development Center	1	6	Upgrade Exterior and Interior Lighting	Completed
Career Development Center	1	7	Electrical Upgrades	Completed

School	Project	Fact	Construction Package	Status
3611001	Phase	Sheet	Construction Fundage	Status
	111000	No.		
Chastain Middle	2	1	Site Drainage Underneath Building and Parking Lot	Construction
Chastain Middle	2	2	North Egress Portico and Walkway Repair	Completed
Chastain Middle	2	3	Front Retaining Wall Repairs	Remaining
Chastain Middle	2	4	Restroom Renovations	Construction
Chastain Middle	2	5	Upgrade Exterior Lighting	Completed
Chastain Middle	2	6	Upgrade Heating, Ventilation, and Air Conditioning Systems - Gym	Remaining
Chastain Middle	2	7	Clean Exterior Building Façade	Completed
Chastain Middle	2	SL	Upgrade Science Labs	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Clausell Elementary	2	1	Structural Repairs	Construction
Clausell Elementary	2	2	Restroom Renovations	Construction
Clausell Elementary	2	3	Electrical Upgrades	Construction
Clausell Elementary	2	4	Upgrade Exterior and Interior Lighting	Construction
Clausell Elementary	2	5	Building Entry Facade Upgrade	Construction
Clausell Elementary	2	6	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Dawson Elementary	2	1	Restroom Renovation - ADA Accessible	Construction
Dawson Elementary	2	2	Upgrade Exterior and Interior Lighting	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
Forest Hill High	1	No. 1	JROTC Building	Construction
Forest Hill High	1	SL	Upgrade Science Labs	Construction
Forest Hill High	1	1	Site Drainage and Soil Erosion Control	Construction
Forest Hill High	1	2	Repair Gymnasium Floor	Construction
Forest Hill High	1	3	Gym (HVAC)	Construction
Forest Hill High	1	4	Exterior and Interior Door Replacements	Completed
Forest Hill High	1	5	Removal of Carpet and Install Tile Flooring	Completed
Forest Hill High	1	6	Restroom Renovation	Completed
Forest Hill High	1	7	Upgrade Exterior and Interior Lighting	Construction
Forest Hill High	1	8	Electrical Upgrades	Completed
Forest Hill High	1	9	Performance Art Space	Construction
Forest Hill High	1	10	Roof Repair	Completed
Forest Hill High	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Green Elementary	1	1	Site Drainage & Soil Erosion Control	Completed
Green Elementary	1	2	Exterior & Interior Door Repairs	Completed
Green Elementary	1	3	Restroom Renovations	Completed
Green Elementary	1	4	Upgrade Exterior & Interior Lighting	Completed
Green Elementary	1	5	Electrical Upgrades	Completed
Green Elementary	1	6	Building Entry Façade Upgrade	Completed
Green Elementary	1	7	Playground Canopy	Completed

School	Project	Fact	Construction Package	Status
School	Phase	Sheet	Construction Fackage	Status
	i nasc	No.		
Hardy Middle	1	1	Site Drainage In the Courtyard and Soil Erosion Control	Completed
Hardy Middle	1	2	Window Replacement	Construction
Hardy Middle	1	3	Exterior and Interior Door Replacement	Construction
Hardy Middle	1	4	Removal of Carpet in the Office	Completed
Hardy Middle	1	5	Upgrade HVAC System	Completed
Hardy Middle	1	6	Restroom Renovation	Remaining
Hardy Middle	1	7	Upgrade Exterior and Interior Lighting	Completed
Hardy Middle	1	8	Handicapped Access Ramps and Lifts	Remaining
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Isable Elementary	1	1	Site Drainage & Soil Erosion Control	Design
Isable Elementary	1	2	Building Entry Façade Upgrade	Remaining
Isable Elementary	1	3	Playground Canopy	Remaining
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Jim Hill High	1	SL	Upgrade Science Labs	Construction
Jim Hill High	1	1	Site Drainage and Soil Erosion Control	Construction
Jim Hill High	1	2	Window Repair and Replacements	Remaining
Jim Hill High	1	3	Exterior & Interior Door Replacement	Remaining
Jim Hill High	1	4	Upgrade HVAC System	Remaining
Jim Hill High	1	5	Restroom Renovation	Construction
Jim Hill High	1	6	Upgrade Exterior & Interior Lighting	Completed
Jim Hill High	1	7	Resurfacing Parking Lots	Construction
Jim Hill High	1	8	Electrical Upgrades	Completed
Jim Hill High	1	9	Upgrade Building Entry Ramp & Railing	Remaining
Jim Hill High	1	10	Building Entry Façade & Door Improvements	Completed
Jim Hill High	1	Added	Gym Floor & Bleacher	Construction
Jim Hill High	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
John Hopkins Elementary	2	No. 1	Electrical Upgrades	Completed
John Hopkins Elementary	2	2	Parking Drive Improvement	Construction
John Hopkins Elementary	2	3	Building Entry Facade Upgrade	Construction
John Hopkins Elementary	2	4	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet	33	0.000
		No.		
Johnson Elementary	2	1	Restroom Renovation - ADA Accessible	Remaining
Johnson Elementary	2	2	Upgrade Exterior and Interior Lighting	Remaining
Johnson Elementary	2	3	Structural Repairs	Construction
Johnson Elementary	2	4	Building Entry Facade Upgrade	Construction
Johnson Elementary	2	5	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Key Elementary	2	1	Exterior and Interior Door Replacements	Construction
Key Elementary	2	2	Building Entry Facade Upgrade	Completed
Key Elementary	2	3	Playground Canopy	TBD

School	Project	Fact	Construction Package	Status
301001	Phase	Sheet	Construction Fackage	Status
	Tilase	No.		
Kirksey Middle	1	1	Site Drainage & Soil Erosion Control	Design
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Lake Elementary	2	1	Site Drainage and Soil Erosion	Remaining
Lake Elementary	2	2	Exterior and Interior Door	Remaining
Lake Elementary	2	3	Plumbing and Restroom Renovations	Construction
Lake Elementary	2	4	Upgrade Exterior and Interior Lighting	Construction
Lake Elementary	2	5	Electrical Upgrades	Construction
Lake Elementary	2	6	Building Entry Facade Upgrade	Remaining
Lake Elementary	2	7	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Lanier High	1	SL	Upgrade Science Labs	Completed
Lanier High	1	1	Repair Under Building	Construction
Lanier High	1	2	Window Restoration	Construction
Lanier High	1	3	Exterior & Interior Door Replacement	Construction
Lanier High	1	4	Restroom Renovations	Construction
Lanier High	1	5	Upgrade Exterior and Interior Lighting	Construction
Lanier High	1	6	Electrical Upgrades	Construction
Lanier High	1	7	Resurface Rear Parking Lots	Construction
Lanier High	1	8	Repair and Widen Pedestrian Walkways	Construction
Lanier High	1	9	Upgrade Building Walkway	Construction
Lanier High	1	10	Building Entry Façade	Construction
Lanier High	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
Laster Elements	2	No.	City During a	Constanting
Lester Elementary	2	1	Site Drainage	Construction
Lester Elementary	2	2	Window Replacements	Construction
Lester Elementary	2	3	Exterior and Interior Door Replacements	Construction
Lester Elementary	2	4	Electrical Upgrades	Construction
Lester Elementary	2	5	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet No.		
Marshall Elementary	2	1	Window Replacements	Remaining
Marshall Elementary	2	2	Exterior and Interior Door Replacements	Construction
Marshall Elementary	2	3	Restroom Renovations	Construction
Marshall Elementary	2	4	Upgrade Exterior and Interior Lighting	Completed
Marshall Elementary	2	5	Electrical Upgrades	Completed
Marshall Elementary	2	6	Building Entry Facade Upgrade	Completed

School	Project	Fact	Construction Package	Status
5611001	Phase	Sheet	Constitution i damage	Status
		No.		
McLeod Elementary	2	1	Site Drainage	0
McLeod Elementary	2	2	Window Repairs	Design
McLeod Elementary	2	3	Exterior Door Replacements	Design
McLeod Elementary	2	4	Upgrade Exterior Lighting	0
McLeod Elementary	2	5	Electrical Upgrades	Design
McLeod Elementary	2	6	Building Entry Facade Upgrade	0
McLeod Elementary	2	7	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
McWillie Elementary	2	1	Site Drainage	Design
McWillie Elementary	2	2	Concrete Walkway Repair	Design
McWillie Elementary	2	3	Interior Painting	Completed
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
	_	No.		
Murrah High	1	1	Site Drainage and Soil Erosion Control	Construction
Murrah High	1	2	Exterior Door Replacement	Completed
Murrah High	1	3	Restroom Renovation	Construction
Murrah High	1	4	Upgrade Exterior and Interior Lighting	Completed
Murrah High	1	5	Interior Corridor Gate Control	Remaining
Murrah High	1	6	Repair and Widen Pedestrian Walkway	Completed
Murrah High	1	7	Upgrade Building Walkway	Construction
Murrah High	1	8	Building Entry Façade Upgrade	Completed
Murrah High	1	SL	Upgrade Science Labs	Completed
Murrah High	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.	lau a l	
North Jackson Elementary	2	1	Site Drainage	Construction
North Jackson Elementary	2	2	Plumbing Repairs	Construction
North Jackson Elementary	2	3	Removal of Carpet and Install Tile Flooring	Construction
North Jackson Elementary	2	4	Upgrade Exterior and Interior Lighting	Construction
North Jackson Elementary	2	5	Electrical Upgrades	Completed
North Jackson Elementary	2	6	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
Northwest Middle	2	No. SL	Upgrade Science Labs	Construction
Northwest Middle	2	1	Site Drainage and Soil Erosion Control	Remaining
Northwest Middle	2	2	Removal of Carpet and Install Tile Flooring	Construction
Northwest Middle	2	3	Upgrade Heating, Ventilation, and Air Conditioning Systems	Completed
Northwest Middle	2	4	Upgrade Exterior and Interior Lighting	Completed
Northwest Middle		5	Resurface Parking Lots	Remaining
NOI LIIWEST MIIUUIE	2	5	Incominant Larking Loro	remaining

Cabaal	Duningt	Fast	Construction Backers	Chahua
School	Project Phase	Fact Sheet	Construction Package	Status
	Pilase	No.		
Oak Forest Elementary	2	1	Site Drainage and Soil Erosion Control	Construction
Oak Forest Elementary	2	2	Window Replacements	Construction
Oak Forest Elementary	2	3	Exterior and Interior Door Repairs	Construction
Oak Forest Elementary	2	4	Restroom Renovations	Construction
Oak Forest Elementary	2	5	Upgrade Exterior and Interior Lighting	Completed
Oak Forest Elementary	2	6	Repair Parking Lot	Construction
Oak Forest Elementary	2	7	Electrical Upgrades	Construction
Oak Forest Elementary	2	8	Building Entry Facade Upgrade	Construction
Oak Forest Elementary	2	9	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
301001	Phase	Sheet	Construction rackage	Status
	Tilase	No.		
Obama Magnet Elementary	1	1	Repair Parking Lot	Completed
Obama Magnet Elementary	1	2	Building Entry Protection Awning	Completed
Obama Magnet Elementary	1	3	Playground Canopy	Completed
Obama Magnet Elementary	1	Added	Multipurpose Room Improvements	Completed
Obama Magnet Elementary	1	Added	Interior Painting	Completed
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Pecan Park Elementary	2	1	Structural Repairs	TBD
Pecan Park Elementary	2	2	Site Drainage and Soil Erosion Control	0
Pecan Park Elementary	2	3	Restroom Renovations	TBD
Pecan Park Elementary	2	4	Upgrade Exterior and Interior Lighting	TBD
Pecan Park Elementary	2	5	Resurface Parking Lots	0
Pecan Park Elementary	2	6	Electrical Upgrades	TBD
Pecan Park Elementary	2	7	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Peeples Middle	2	SL	Upgrade Science Labs	Construction
Peeples Middle	2	1	Upgrade Exterior and Interior Lighting	Pending
Peeples Middle	2	2	Electrical Upgrades	Pending
Peeples Middle	2	3	Restripe Parking Lot	Pending
Peeples Middle	2	4	Level Play Field	Completed
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Powell Middle	2	SL	Upgrade Science Labs	Construction
Powell Middle	2	1	Window Repairs and Replacements	Construction
Powell Middle	2	2	Exterior and Interior Door Replacements	Construction
Powell Middle	2	3	Restroom Renovations	Construction
Powell Middle	2	4	Upgrade Exterior and Interior Lighting	Completed
Powell Middle	2	5	Resurface South Drive	Completed
Powell Middle	2	Added	HVAC Upgrades	Completed

School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Provine High	1	SL	Upgrade Science Labs	Completed
Provine High	1	1	Drainage & Plumbing Underneath Building	Completed
Provine High	1	2	Interior Corridor Control Gate	Remaining
Provine High	1	3	Exterior and Interior Door Replacement	Construction
Provine High	1	4	Restroom Renovations	Completed
Provine High	1	5	Upgrade Exterior and Interior Lighting	Completed
Provine High	1	6	Repair Student and Teacher Parking Lots	Completed
Provine High	1	7	Building Entry Façade Upgrade	Remaining
Provine High	1	8	Kitchen Plumbing Repair	Completed
Provine High	1	Added	HVAC Upgrades	Completed
Provine High	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Raines Elementary	2	1	Site Drainage and Soil Erosion Control	Construction
Raines Elementary	2	2	Restroom Renovations	Construction
Raines Elementary	2	3	Building Entry Facade Upgrade	TBD
Raines Elementary	2	4	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Shirley Elementary	2	1	Exterior and Interior Door Repairs	Construction
Shirley Elementary	2	2	Upgrade Exterior and Interior Lighting	Construction
Shirley Elementary	2	3	Electrical Upgrades	Construction
Shirley Elementary	2	4	Building Entry Facade Upgrade	Construction
Shirley Elementary	2	5	Playground Canopy	TBD
Shirley Elementary	2	Added	Restroom Renovations	Construction
Shirley Elementary	2	Added	Sidewalk and Ramp Replacement	Construction
Shirley Elementary	2	Added	Classroom Millwork and Sinks	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
Smith Elementary	2	No. 1	Window Replacements	Remaining
Smith Elementary	2	2	Plumbing Repairs	Construction
Smith Elementary	2	3	Exterior Door Replacements	Remaining
Smith Elementary	2	4	Restroom Renovations	Construction
Smith Elementary	2	5	Electrical Upgrades	Construction
Smith Elementary	2	6	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
3611001	Phase	Sheet	Constitution i delide	3.0.03
		No.		
Sykes Elementary	2	1	Plumbing Repairs	Construction
Sykes Elementary	2	2	Exterior Cleaning	Remaining
Sykes Elementary	2	3	Restroom Renovations	Construction
Sykes Elementary	2	4	Electrical Upgrades	Construction
Sykes Elementary	2	5	Playground Canopy	TBD

School	Project	Fact	Construction Package	Status
3611001	Phase	Sheet	construction ruckage	Status
		No.		
Van Winkle Elementary	1	1	Improve Back Parking Lot Surface	Completed
Van Winkle Elementary	1	2	Interior Painting	Completed
Van Winkle Elementary	1	3	Electrical Upgrades	Completed
Van Winkle Elementary	1	4	Upgrade Exterior Lighting	Completed
Van Winkle Elementary	1	5	Upgrade Front Entrance Security	Completed
Van Winkle Elementary	1	6	Interior Door Repairs and Replacements	Completed
Van Winkle Elementary	1	7	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Walton Elementary	1	1	Interior Door Repairs and Replacements	Remaining
Walton Elementary	1	2	Restroom Renovations	Construction
Walton Elementary	1	3	Electrical Upgrades	Construction
Walton Elementary	1	4	Building Entry Facade Upgrade	Remaining
Walton Elementary	1	5	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Wells APAC Elementary	2	1	Walkway Repairs	Design
Wells APAC Elementary	2	2	Upgrade Exterior Lighting	Completed
Wells APAC Elementary	2	3	Drainage Repair	Design
Wells APAC Elementary	2	4	Plumbing Repairs	Design
Wells APAC Elementary	2	5	Electrical Upgrades	Design
Wells APAC Elementary	2	6	Performing Arts Upgrades	Design
Wells APAC Elementary	2	7	Building Entry Awing and Facade Upgrade	Design
Wells APAC Elementary	2	8	Playground Canopy	TBD
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Whitten Middle	2	SL	Upgrade Science Labs	Construction
Whitten Middle	2	1	Reroof	Construction
Whitten Middle	2	2	Waterproof Walkway and Building Joints	Construction
Whitten Middle	2	3	Restroom Renovations	Remaining
Whitten Middle	2	4	Upgrade Exterior and Interior Lighting	Completed
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Wilkins Elementary	1	1	Repair Walkway and Entrance Steps	Completed
Wilkins Elementary	1	2	Soil Erosion Control	Construction
Wilkins Elementary	1	3	Exterior and Interior Door Repairs and Replacements	Construction
Wilkins Elementary	1	4	Restroom Renovations	Construction
Wilkins Elementary	1	5	Upgrade Exterior and Interior Lighting	Completed
Wilkins Elementary	1	6	Electrical Upgrades	Completed
Wilkins Elementary	1	7	Building Entry Façade Upgrade	Construction
Wilkins Elementary	1	8	Playground Canopy	TBD

School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Wingfield High	1	SL	Upgrade Science Labs	Construction
Wingfield High	1	1	Site Drainage & Soil Erosion Control	Completed
Wingfield High	1	2	Restripe Parking Lot	Completed
Wingfield High	1	3	Restroom Renovations	Completed
Wingfield High	1	4	Upgrade Exterior and Interior Lighting	Completed
Wingfield High	1	5	Building Entry Façade	Completed
Wingfield High	1	L&A	Library & Academy	Construction
School	Project	Fact	Construction Package	Status
	Phase	Sheet		
		No.		
Hughes Field	1	1	Hughes Field	Construction
South Jackson Field	1	2	South Jackson Field	Construction
Baseball Complex	1	4	Baseball & Softball Complex	Design
Newell Field	1	5	Newell Field	Design