

Radon Testing Results - Bandon SD Gymnasium

Action Level is 4.0 pCi/L

Site Name	Building Name	Room Description (per floor plan)	Kit serial #	Date sampled	Type of test	Results (pCi/L)
BSD Gymnasium	Main Building	2nd Floor Main Office	4453260	3/28/2018	Detector Kit	0.2
BSD Gymnasium	Main Building	Basement Office	4337194	3/28/2018	Detector Kit	0.2
BSD Gymnasium	Main Building	Basement Office	4525821	3/28/2018	Detector Kit	0.2
BSD Gymnasium	Main Building	2nd Floor Other	4525874	3/28/2018	Detector Kit	0.2
BSD Gymnasium	Main Building	Basement Office	4607947	3/28/2018	Detector Kit	0.2
BSD Gymnasium	Main Building	Basement Office	4525669	3/28/2018	Detector Kit	0.2
BSD Gymnasium	Main Building	Basement Office	4525766	3/28/2018	Detector Kit	0.2
BSD Gymnasium	Main Building	Basement Other	4525939	3/28/2018	Detector Kit	0.2